




STRUCTUREPOINT - CORRECTIVE ACTION REPORT

Program Name	CAR No	Revision	Date
spMats	M001	0.0	2/26/16

Issue Description	During copying and pasting of the updated loads from an external source into an existing loads table, the M_y values are set to zero when the user navigates to other tabs. This occurs without notifying the user that the updated values have not been correctly pasted.
Typical GUI Path(s)	Define Loads Concentrated
Version Found	v8.00
Issue Status	Corrected v8.11
Corrective Action	Users should review models created in v8.00/v8.10 if copy and paste was used to import M_y to ensure M_y load values are correctly transferred. If values are not correctly transferred, the user must enter the correct values manually or alternately contact StructurePoint for assistance.
Workaround for Uncorrected Version	<ol style="list-style-type: none"> 1. The user can import loads from a text file by clicking Import Button under Define Loads Concentrated instead of utilizing copy and paste feature. 2. Manual text input of M_y values

	Software Mgr.	Engineering Mgr.	Operations Mgr.
Authorized Signature			
Approval Date	3/16/16	3/16/16	3/16/16